RADIATION SAFETY PROGRAM

Office of Environmental Health and Safety

Revision: September 18, 2023

H. Using only the radioactive material for which they are licensed, and only for those uses specifically authorized.

I. Informing the Radiation Safety Officer of changes in procedure which may increase the probability of radiation exposure or laboratory contamination.

J. Establishing appropriate procedures to ensure that radioactive materials are properly labeled.

K. Establishing that radioactive materials are properly controlled within his or her project, and that they are properly stored at the end of each workday.

L. Assuring that the laboratory is equipped with adequate survey and/or monitoring equipment to aid in the safe handling of radioactive material and performing routine surveys of work areas as required.

M. Ensuring that maintenance personnel are not permitted to work on equipment, hoods, or sinks in radioactive materials use areas without the presence of a knowledgeable member of the laboratory staff to provide specific information.

N. Complying with proper procedures for termination of work using radioactive materials. The authorized user must return to the Radiation Safety Officer all radioactive materials, including waste, assigned to him or her under the license. Particular care should be exercised to see that specialized equipment such as personnel monitoring devices, survey instruments and shielding materials are returned to the Radiation Safety Officer. A final termination survey is also necessary.

O. Ensuring that the following individual user responsibilities are discharged by those under their control.

P. Know and understand how to use the monitoring tools available in each Department so that information can be collected quickly in the absence of the RSO/RST.

The Administration commits to authorizing the Authorized Users to stop any unsafe operation by individual users.

7. RESPONSIBILITIES OF INDIVIDUAL USERS

Individual users include all radiation workers, including those operating under the direct supervision of an authorized user. Each individual user of radioactive materials is responsible for:

A. Keeping exposure to radiation as low as possible, and specifically below those levels specified for maximum exposure in the Maine Radiation Regulations.

B. Wearing the prescribed monitoring equipment, such as film badges and TLD ring dosimeters, in radiation areas. Personnel who work only with pure alpha emitters or only with pure beta emitters having a maximum energy of less than 0.2 MeV (e.g., 3-hydrogen, 14-carbon, 35-sulfur) will not be required to wear film badges (see Section 12; Attachment 4).r 7TjEMC /P2. A.tte

9. AMENDMENTS TO ESTABLISHED RADIOISOTOPE USE

Application for amendment to an approved application should be made in writing to the Radiation Safety Officer f

Excessive contamination levels (more than 1000 dpm/100 cm^2) shall be brought to the attention of the RSO, and the area in question shall be decontaminated and resurveyed. Action levels for removable surface contamination are outlined in Table 1.

Reports on the surveys shall be reviewed by the RSO and kept on file in the Radiation Safety Notebook. The authorized user of the project shall ascertain that the necessary survey equipment is available to perform the required procedures and that a specific individual is assigned the tasks. The Radiation Safety Officer is available to assist in setting up an appropriate survey program for each project.

TABLE 1
ACTION LEVELS FOR REMOVABLE SURFACE CONTAMINATION

Type of Surface	Alpha Emitters (dpm/l00cm^2)	Beta or X-ray Emitters (dpm/l00cm^2)
Unrestricted areas	22	220
Restricted areas	220	2200
Personal clothing worn outside restricted areas	22	220
Protective clothing worn only in restricted areas	220	2200
Skin	220	220

Averaging is acceptable over non-living areas of up to 300 cm^2 or, for floors, walls, and ceiling, 100 cm^2. Averaging is also acceptable over 100cm^2 for skin or, for the hand10.08 scEMC fp

cleaned and tested for contamination before being decommissioned.

Disposal of radioactive wastes will be conducted in accordance with Maine Rules [10-144A CMR 220.D.33-39

conformity with Maine Rules [10-144A CMR 220.D.27-30] and OSHA workplace requirements, which will contain the words “CAUTION, RADIATION AREA”. These postings shall be installed or re

Reports of the National Council on Radiation Protection and Measurements:

ATTACHMENT 1. CURRENT COMMITTEE MEMBERS (2023-2024)

Radiation Safety Committee Members

Name	Department	Contact Number
Phil Camill (Chair)	Earth & Oceanographic Science	207-721-5149
Karen Topp	Physics and Astronomy	207-725-3611
Charly Wojtysiak (RSO)	Facilities Management	207-798-4132
Rene Bernier	Chemistry	207-725-3162
Martha Mixon (RST)	Biology/Instrument Support Technician	207-725-3588
Ken Dennison	Physics/Electronics Lab Instructor	207-798-4315

APPLICATION FOR PERMISSION TO USE RADIOACTIVE MATERIALS (con't)

4. List equipment for handling isotope. (NOTE: dry smears, using filter paper and counted in a liquid scintillation counter, should be utilized in surveying work areas and equipment for radioactive contamination resulting from work with 14-carbon, 3-hydrogen and 35-sulfur).

Hood	( )	Appropriate Warning Signs and Labels	( )
Shielding	( )	Waterproof-backed absorbent material for	
Disposable Gloves	( )	bench and floor coverings	( )
G.M. Survey Meter	( )	Appropriate Monitoring Devices	( )
Mechanical Pipette	( )	Handling Tongs	( )
Stainless Steel Sink	( )	Air Sampling Equipment	( )
Shielded Storage Containers	( )	Glove Box	( )
Beta or gamma counters	( )	Lab Coats	( )

Other Special Equipment or Facilities:

5. Waste Disposal:

a. Soluble low level liquid waste into sink in Building: _____ Room: _____

b. Dry solid waste into labeled container in Building: _____ Room: _____

c. Will there be other wastes generated (animals, insoluble liquids, scintillation fluids, etc.)?

Yes ( ) No ( )

If yes, outline description and disposal W (tt)1Tc 0 o 3 (w)-2. Td[(r)a2 (l)(g)11. 2.u7 Tc

ATTACHMENT 5. RADIOISOTOPE RECEIPT LOG

Isotope _____ Date of Receipt _____

Amount _____ Lot Number _____

Vendor _____ Purchase Order Number _____

Exposure rate at 1 meter: _____ mR/hr

Exposure rate at surface: _____ R/hr

Wipe Results: _____ cpm

Packaging intact? Yes ( ) No ( ) Inner label legible? Yes ( ) No ( )

Final container intact? Yes ( ) No ( ) Packing material ok? Yes ( ) No ( )

CoCID 20 >>BDC -0.014 Tc 0.014 Tw TP /4MCID 55 >>BDC -0.014 Tc -0.011 Tw 9.96 0 0

ATTACHMENT 6. RADIATION SITE MONITORING LOG

Name: _____ Date: _____

Location: Building: _____ Room: _____

Exact location(s) in room: _____

_____

_____

Check one: ( ) Suspected spill

( ) Routine monitoring

Survey meter: _____ mR/hr

Wipe results: _____ cpm

O RADIOISOTOPE STUDIES

ols have been approved and you may provide

DURATION OF USE: _____

Room: _____

Revised 09.18.2023

ATTACHMENT 8. PROCEDURES FOR RADIOISOTOPE STUDIES IN VIVO

INITIATION OF RADIOISOTOPE STUDIES IN VIVO

Prior to the start of radioisotope studies in vivo, an investigator must be an Authorized User of Radioisotopes under our N.R.C. License, and:

1.

3. Cage changing schedules will be individually designed for each experiment by the Authorized User. However, cages, water bottles and bedding must be changed at least once a week.

4. Handling animals in disposable cages:

    a. Cover bench top with absorbent paper before opening cages. Decontaminate all equipment such as forceps and forceps jar with Count-Off or Radia-wash. All waste materials are to be properly packaged and labeled for transfer to the radioactive waste storage area.
    b. Cages containing radioisotope contaminated bedding are emptied into the receptacle provided and isotope/activity/date/user logged on the attached waste disposal card.
    c. Disposable cages are placed in bags, similarly labeled and arrangements made through the Radiation Safety Officer for proper disposal. **Disposable cages may NOT be washed and reused.**
    d. Water bottles, which have been dedicated for exclusive use in the radioisotope animal room, cage lids and any non-disposable cages are washed in the Animal Housing Facility on a separate schedule with appropriate segregation and monitoring by the Radiation Safety Officer.
    e. Authorized Users or their assistants are expected to clean up bench tops, vacuum or damp mop the floor if food or bedding is spilled, and maintain all other animal room housekeeping standards.

5. In the case of long term studies (over 1 week) animals may be transferred from disposable to non-disposable cages after the majority of the radioactive material has been excreted and levels in bedding are essentially background. Per Radiation Safety review.

MONITORING OF THE WORK AREA

The Authorized user or his/her assistant are to complete monitoring responsibilities commensurate with other radioactive materials use during the course of the in vivo study. Positive wipe test or surm[(s)-614 Tw [(es)-8 ( )]TJ0.001 Tw1th